Now is the time to have your equipment inspected by our Factory Trained Technicians!

APACHE

OVA Winter Inspection Program



SPRAYER INSPECTION \$695.00



Comprehensive On-Farm Inspection Service For Apache Sprayers







APACHE INSPECTION INCLUDES:

- Full product system check including rate control
- Boom accumulators pressure check
- Suspension cylinder & accumulator check
- Boom system check and necessary adjustments
- Hydraulic pressure checks
- And much more

INSPECT TO PROTECT! CALL TODAY! \$695.00

(Service Call Fee Included)

Locations & Contacts:

Owensboro, KY 270-684-4202 David Boarman Aussellville. KY 270-725-8948 David Boarman

Greensburg, IN 812-222-1220 David Boarman Decatur, IL 800-254-7514 Keith Roberts

www.ohiovalleyag.com

Key Points of Inspection



Boom Accumulators

Boom accumulators act as the hydraulic shock for the booms. Having the proper 200 PSI in the accumulator extends the life of the boom. Without proper charge the booms become rigid and begin to develop cracks around hinge points eventually leading to boom failure.



Drive Line

To keep sprayer efficiently moving, we will inspect u-joints and all drive line components.



Front Strut

The strut is the front suspension of the sprayer. To maintain a comfortable ride, we will check the accumulator pressure and travel of the front struts to ensure they are within specifications.



Three main areas to inspect on the hydraulic pump:

- 1) *Hydraulic Pressure* ensures hydraulic system is working at peak performance.
- 2) *Hydraulic Suppressor* Look for a charge pressure of 1200 PSI to keep hydraulic system running quietly.
- 3) **Hoses** Check hydraulic hoses for any signs of wear to prevent failure in the hydraulic system.



Rear Suspension

Check the operation of the rear suspension hydraulic cylinders and the rear suspension accumulator pressures to maintain a comfortable ride in the sprayer. Also look for proper cylinder height adjustment on the rear suspension cylinders to ensure they are within specifications.

Product Plumbing

Inspect condition and operation of product plumbing, electrical connections, boom valves, pressure control valve, and flowmeters.

Monitors & Precision

Go through monitor and precision equipment settings to confirm all systems are functioning correctly.









Envizio Pro II

Cruizer II

SCS-4400

Service & Pricing

	2011-2013	2009-2010
Complete Service	\$1,232.82	\$988.32
Engine	\$437.08	\$302.72
Transmission	\$248.70	\$211.46
Differential & Final Drives	\$207.62	\$207.62
Hydraulic Filter	<i>\$164.34</i>	\$73.20

[&]quot;Service call fee not included in above listed pricing"

"An additional service call fee will be applied for servicing of the machine or for a return trip if needed for inspection repairs. Due to the length of the inspection and potential winterization we are unable to complete a full service in the same day."

Please contact the service department for pricing if year/model is not listed.

Complete Service includes oil, fuel, transmission, hydraulic, cab, and air filters.

Along with all engine, transmission, differential, and planetary fluids.

Excludes hydraulic oil.

***Service call fee is for service of machine or additional repairs.

Inspection service call fee is included in \$695.



PO Box 21159 Owensboro, KY 42304



Locations & Contacts:

Owensboro, KY 270-684-4202

David Boarman

Russellville, KY 270-725-8948

David Boarman

Greensburg, IN 812-222-1220 David Boarman

Decatur, IL 800-254-7514 Keith Roberts